

June 27, 2019

BWARI Biofilter Rehabilitation Converting a Liability into an Asset

BUILDING A WORLD OF DIFFERENCE®








Agenda

- City of Columbus Collection System Odor **Control Facilities**
- BWARI Biofilter Background
- Condition Assessment
- Ventilation Evaluation
- Biofilter Rehabilitation Design
- Construction & Start Up

City of Columbus Odor Control Facilities




City of Columbus Odor Control Facility Locations

- Upper Scioto West Interceptor Sewer (USWIS) Biofilters
- Olentangy Scioto Interceptor Sewer (OSIS)
 Downtown Biofilters
- Big Walnut Augmentation and Rickenbacker Interceptor (BWARI) Biofilter
- Lockbourne Intermodal Subtrunk (LIS) Biofilters
- Blacklick Creek Interceptor Sewer (BCIS) Biofilter

The City maintains 3,300 miles of sanitary and combined sewers.

BWARI Biofilter Background




Collection System

- Big Walnut Augmentation and Rickenbacker Interceptor (144")
- Big Walnut Outfall Sewer (108")
- Big Walnut Trunk Sewer (96")
- Alum Creek Trunk Sewer (102")
- Blacklick Trunk Sewer (96")

Average flow in BWO upstream of BWARI was 70 MGD (2014).

BWARI Biofilter Site Layout





Facility History

- Constructed in 2009
 - 23,500 CFM
 - Numerous Start Up Issues
- 2012-2013 "Repairs"
 - Bypassed multiple systems to get fans running
 - Irrigation/Humidification issues
 - Issues with BBX
 - Air flow reduced to 8,000 CFM due to odor complaints
- RFP for Rehabilitation Issued in 2014
- AFD for Fan #1 failed mid-2015
- AFD for Fan #2 failed in early 2016

Condition Assessment









Biofilter

- Ductile Iron Drain Lines
- Foul Air Duct and Pipe
- Fan Maintenance
- Biofilter Media
- Biofilter Concrete
- Scrubber






Humidification System

- Humidification System
 - NPW
 - Boiler
 - Spray Nozzles
 - Recirculation Pumps
 - Controls
- In-Bed Irrigation Failure

The system complexity resulted in numerous failures.










Fan Building

- MAU & Vent Fans
- Electrical Room A/C
- AFD
- Electrical Panels
- Instrumentation
- PLC





BBX

- Slide Gates & Weir Gates
- Level
- PLC & Radio
- Actuators
- RTC






Ventilation Evaluation



Ventilation Evaluation

- Determine Required Ventilation Rate
 - Control Odor (Negative Pressure)
 - Reduce Corrosion
 - Multiple Scenarios
- Characterize Foul Air Stream
 - Seasonal Effects
 - Loading Rates





Study Area

- Sampling
 - March 2014
 - August/September 2014


SAMPLE POINT	LOCATION	ODALOG	DIFFERENTIAL PRESSURE
1	ACT-S	X	X
2	BWN	X	X
3	BLC	X	
4	BWO	X	X
5	BBX	X	
6	BWO	X	
7	BWARI	X	X
8	Biofilter	X	



Winter Sampling Results

- March 2014
 - Biofilter Inlet Only
 - 8,000 CFM
 - H2S
 - Average: 2 ppm
 - Maximum: 25 ppm

Sampling Results



0.06 0.13 0.19 0.25 0.31 0.38 0.44 0.56 0.56 0.69 0.75 WASTEWATER

Figure 1
Idealized Air Velocity Contours in Percent of Wastewater Velocity




Ventilation & Corrosion

- Ventilation Modelling
 - Average Dry Weather Flow from SWMM Model
 - Pescod & Price Method
 - ACT + BLC + BWT > BWO = Pressurization
 - Field Work Confirmed Modelling Results

Corrosion

- City Rehabilitating BWO, ACT and BWT
- Historic Corrosion in BWO: 23 yrs for 1 inch
- Model Predicts 25 yrs for BWO at 10 ppm H₂S
- Trunk Sewer Life Extended Significantly
 - Lower H₂S

Biofilter Rehabilitation



Recommended Improvements

- Increase Air Flow to 35,000 CFM
 - Raise Cell Walls
- Remove, Screen and Reuse Lava Rock
- Install New Organic Media
- Keep Hallsten Floor System
- Rehabilitate Concrete
- Install Corrosion Protection Lining System



Recommended Improvements

- Remove Existing Humidification and Irrigation
- Install New Simplified Irrigation System
- Fan Maintenance
- Replace MCC
- Replace PLC
- Rectify Radio Communication Issues

Recommended Improvements

- Replace Hazardous Gas Monitoring System
- Replace and Simplify HVAC Systems
- Replace BBX Actuators
 - Position Indication
 - RTC Considerations
- Add Level and Flow Sensing

Keeping dry weather flows in the BWO reduced H₂S levels in the collection system significantly.

Construction & Start Up



Construction Start August 2016

- Raised Wall
- Removed Existing Media



And Then....



Concrete Corrosion

- Corrosion Significantly Worse Than Expected
 - 2-year Period Between Condition Assessment and Construction
 - Could Not Inspect Biofilter Floor
- Contract Included Significant Allowance





Changes in Scope


- Installed New Concrete Floor in Cells
- Changed to HDPE Liner
- Added FRP Pipe Header
- Hallsten Floor Replacement



BWARI Biofilter November 21, 2016

Plenum Floor

Hallsten Floor Issues











"Plumbing" Issues

- Tunnel Venting Through Building Plumbing Vents
 - Odors Prevalent at Site with Fans & Dampers Off
- Plumbing Vent Penetration in Electrical Room
- Added Trap on Sanitary Lateral






And Then.....

- Fan Motors
 - Fans Failed in 2015 and 2016
 - Motors Leaking Grease in early 2017
 - Replaced both Fan Motors
- BBX Gate Coupling Failure
 - Bronze Couplings Failed
 - Stainless Steel Couplings Installed







Start Up

- Media Replacement
- Commissioning
 - Operational Demonstration
 - System Reliability
 - >99% Removal of H₂S









Conclusion

- Ventilation Evaluation was Critical
 - Confirmed Required Airflow
 - Dry Weather Flow Diversion
- Condition Assessment
 - Be as Thorough as Possible
- Change is the Only Constant
- Simple & Reliable Operation Achieved
- All Work Completed for Original Contract Amount
 - \$3,606,900 Bid Amount
 - \$3,597,829 Final Cost

Special Thanks to:

- City of Columbus
 - Nick Domenick
 - Jeremy Cawley
 - Greg Fedner
 - Larry Lamp
- The Righter Company

- PRIME AE Group
- CDM Smith
- HWS
- Hatch
- DLZ

The success of the project was due to a collaborative effort between the City, Contractor, Construction Manager and Design Team.



BUILDING A WORLD OF DIFFERENCE

Lee Weber, P.E.

+1 614-454-4398 WeberL@bv.com

Nick Domenick, P.E.

+1 614-645-4693 NJDomenick@Columbus.gov June 27, 2019





BUILDING A WORLD OF DIFFERENCE®