

KEYS TO AN EFFECTIVE GI OPERATIONS AND MAINTENANCE PROGRAM

June 27th 2019



Bill Landshof, PE
Principal Water Engineer

Kurt Kinney, PE
Staff Water Engineer

Four Elements for Success



Four Elements for Success





Workforce: Key Players



Routine Maintenance
Worker



Skilled
Inspectors



Program Manager



Data Management
Specialist



Subject Matter Experts
(Plant, Tree,
Engineering)



Workforce – Importance of Experts




Plant Expert Address
planting issues and
plant health concerns






Workforce – Balancing Resources





Workforce – Balanced Recommendation







Four Elements for Success










Recommended Inspection Types

Standard Maintenance Inspections:

-  Mowing
-  Trash removal
-  Plant replacement
-  Mulching

Quality-Related Inspections:

-  Effectiveness
-  Structural repair
-  Regulating overflow
-  Asset integrity
-  Resident concern





Quality Inspection Frequency Options

OPTION 4

Only Inspect After Major Storm Events



OPTION 1

Inspect Monthly




OPTION 3

Potential for the Largest Failure or Resident Impact



OPTION 2





Prioritize Based on Flow & Slope





Maintenance Inspection Guidelines

Seattle Public Utilities Green Stormwater Operations and Maintenance Manual Erosion

Service Level A (Excellent Effort)	Service Level B (Good Effort)	Service Level C (Moderate Effort)	Service D (Poor Effort)
<p>No erosion or bare spots</p> 	<p>Some erosion and bare spots (0-5%)</p> 	<p>Substantial erosion and bare spots (5-10%)</p> 	<p>Completely eroded and bare spots (More than 10%)</p> 

A Picture is Worth a Thousand Words



Maintenance Inspection Guidelines

Seattle Public Utilities Green Stormwater Operations and Maintenance Manual Erosion

Service Level B (Good Effort)	Service Level C (Moderate Effort)	Service Level D (Low Effort)
<p>water infiltrates well, pavers are up to 10% clogged or minimal ponding is observed</p>	<p>water infiltrates well, pavers are between 10-40% clogged and minimal ponding is observed</p>	<p>water does not infiltrate well, pavers are more than 40% clogged</p>

A Picture is Worth a Thousand Words

Transform to a Digital Platform

Microsoft Excel

Collector for ArcGIS by ESRI

Survey 123 for ArcGIS by ESRI

ArcGIS Desktop

SQL Server Reporting Services

Fulcrum

SQL Sync

SQL Server Reporting Services

Create a Software Workflow



Data Collection Tools






Data Collection Tools – Tablet Inspection





Tablet Inspections Deliver One-Touch Reporting



Inspection Items	Present? (Yes/No)	Maintenance needed? (Yes/No)	Inspection Frequency	Comments
Bioretention Facilities				
1. Permanent Structures				
a. Overflow structure/Catch basin	Yes	Yes	M	1a. Debris is present in catch basin.
b. Inlet/Outlet Structure/Curb cut/Curb plate/Grates	No	No	M	1b. Bare spots are evident in turf along rain garden.
c. Basin walls	No	No	M	
d. Outlet Control (i.e. ball valve, Aspdrain, etc.)	Yes	No	M	
e. Inflow pipe headwall	No	No	M	
f. Splash pads	No	No	M	
g. Delineators	No	No	M	
h. Downspouts	No	No	M	
i. Condition of side slopes	Yes	Yes	M	
j. Cleanout	Yes	No	M	
2. Debris Removal				
a. Debris in bioretention and contributing areas?	No	No	M	
b. Leaf and tree debris	No	No	M	
c. Sediment deposition (depth and percent coverage)	No	No	M	
d. Trash	No	No	M	
3. Vegetation				
a. Dead or diseased plants	No	No	M	3c. It appears that the Kims Knee High and Asclepias Tuberosa have not broken dormancy and will be rechecked during a future inspection. All other plants are correct according to planting plans.
b. Prune perennials (during fall)	Yes	No	SA	3d. Bare spots are evident in turf along rain garden.
c. Plant composition according to approved plans	Yes	No	M	3e. Weeds are present in rain garden.
d. Turf	Yes	Yes	M	
e. Weeds	Yes	Yes	M	
f. Vegetation sufficiently watered?	Yes	No	M	
g. Trees and shrubs?	No	No	M	
4. Erosion				
a. Mutch erosion	No	No	A	
b. Biosoil erosion	No	No	M	
c. Shale erosion	No	No	M	
5. Function				
a. Sediment depth greater than 20% of swale design depth	No	No	M	5d. There are bare areas where no vegetation is planted or where plants have not broken dormancy.
b. Filter bed is blocked or filled inappropriately	No	No	A	
c. Vegetation	No	No	M	
d. Sufficient plant coverage	No	Yes	M	
6. Temporary Erosion Controls				
a. Straw wattles/straw bales/straw matting/silt fence			M and S	
b. Inlet protection			M and S	
c. Sediment issues			M and S	
d. Erosion issues			M and S	
e. Standing water			M and S	
f. Side slopes			M and S	
g. Unhealthy plants?				
h. Temporary seeding and mulching				
Inspection Frequency Key A = Annual, SA = Semi-annual, M = Monthly, S = Seasonal				
Summary				
1. Inspector's Remarks: None				
2. Previous maintenance not completed: None				



One Touch Reporting

BLUE PRINT
COLUMBUS
Clear streams. Strong neighborhoods.

PHOTOGRAPHIC LOG

ARCADIS

Rain Garden/Canyon Dr/Glenmont PI Regional Basin

Overall Photo	Date: 9/13/2018	
Direction Photo Taken:	West	
Description:		

Blueprint Clintonville 1 - Cooke / Glenmont
CIP # 650870-100005
Columbus, Ohio

Page 1



One Touch Reporting



Photo No.		Date:
01		9/13/2018
Direction Photo Taken:		
North		
Description:		
Overall photo facing north.		
		

Photo No.		Date:
02		9/13/2018
Direction Photo Taken:		
North		
Description:		
Missing butterfly weed in southwestern area of basin.		
		



Maintenance Inspection Summary

MAINTENANCE INSPECTION SUMMARY SHEET

Project Name	No. of BMPs Inspected this Month	No. of BMPs With Maintenance Items	No. of BMPs With Maintenance Items for 2+ months
Blenheim / Glencoe	0	0	0
Cooke / Glenmont	16	16	5
Morse / Dominion	0	0	0
Overbrook / Chatham	0	0	0
Schreyer / Springs	20	17	0
Weisheimer / Indian Springs	0	0	0



Maintenance Inspection Summary

MAINTENANCE INSPECTION SUMMARY SHEET

Cooke / Glenmont


Recurring for 2+ Mo	BMP Name	BMP ID	Issues at BMP	Comments
	Rain Garden	0000G0130	1a	1a. Debris found in catch basin, needs removal.
X	Rain Garden	0000G0130	2b	2b. Sycamore seeds present in rain garden.
X	Rain Garden	0000G0130	3d	3c. Vegetation is actively growing. Species count will occur after all plants breaks dormancy. 3d. Bare spots evident in turf along rain garden.
X	Rain Garden	0000G0130	4a	4a. Mulch erosion along outer perimeter of rain garden on west end.
	Rain Garden	0000G0324	3e	3c. Vegetation is growing and will be re-evaluated when all plants break dormancy. 3e. Grass is present along the edging of the basin inside the basin and needs to be weeded.
	Rain Garden	0000G0324	4a	4a. Mulch has eroded away at the inlet locations for the downspout redirections.
	Rain Garden	0000G0328	1e	1e. Sediment removal is needed downstream of inflow pipe headwall.

Four Elements for Success





Corrective Action - Process





Corrective Action – Issue





Corrective Action – Three Methods





Typical Corrective Action Issues



Velocity

Inlet Before

Inlet After

Erosion Before

Erosion After



Four Elements for Success





Data Management System


Generate work order from inspection data






Data Analytics

Analyze Maintenance Data for Trends










Data Analytics



Facility	Area	Process	Asset	Max C...	Photos
WWTP	Disinfection	Facility Support	Alarm Annunciator Panel 2		
WWTP	Plant Wide	Old Chlorine Building	Chlorine Building Roof		
Lift Stations	Cottage Ct	Pumping	Level Transducer		
Lift Stations	High Dive Park	Pumping	Level Transducer 2		
WWTP	Primary Clarifiers	Facility Support	Primary Building Roof		
WWTP	Digestion	Digestion	West Digester 3 Cover		
CSO Tanks	New Jackson	Storage	Wetwell		
WWTP	Final Clarifiers	Secondary Settling	Float Switch 2		
WWTP	Aeration Tanks	Aeration	Gate 4A, Aeration Tank 4 (Abandoned)		
WWTP	Plant Wide	Westside South Storage Building	Unit Heater 1, Westside South		






Leveraging Best Practices


Design Feedback Loop

Utilizing the inspection data to implement design and construction improvements for future GI assets





Residential Input



Phone Application
Utilizing resident feedback
as a real-time indicator





Feedback Changes

BEFORE



AFTER



SAFETY-RELATED BEST PRACTICES:

- 4:1 SLOPE RATIO
- SAFETY STRIP
- DELINEATORS



Feedback Design Change





Beautiful Raingardens



Questions?



Bill Landshof, PE
Principal Water Engineer
Bill.Landshof@Arcadis.com



Kurt Kinney, PE
Staff Water Engineer
Kurt.Kinney@Arcadis.com