

**SEOWEA LAC Meeting**  
**Monday, September 18, 2017 – Columbus, Ohio**

<b>Hosts:</b>	City of Columbus, Ohio Jackson Pike WWTP <b>ELECTRONIC PRE-REGISTRATION PREFERRED</b>
<b>Check-In:</b> 9:30-10:00	Jackson Pike WWTP
<b>Tours:</b>  10:00-11:00	Tour of Jackson Pike Wastewater Treatment plant  (1.0 contact hrs)
<b>Lunch:</b> 11:30-12:30	City of Columbus Fairwood Ave Complex 1250 Fairwood Ave Columbus, OH 43206 614-645-1239
Lunch Sponsored by Thomas Scientific	
<b>Business Meeting:</b> 12:30	Committee business
<b>Technical Sessions:</b>	
12:30-1:30	<i>2017 100% Beneficial Reuse-City of Columbus transition from incineration to Beneficial Resuse Outlets</i> Heather Curtis, Columbus(1.0 ct hr)
1:30-2:30	Laboratory and Operator Certification Challenge Melodi Clark City of Columbus (1.0 ct hr)
2:30-3:30	Surveillance Lab Tour Mike Heniken City of Columbus (1.0 ct hr)

Contact Hours Applied For 4.0

Tour, lunch and technical session is free for first time attendees.

P.O. forms can be addressed to the attention of Melodi Clark at Southeast Section OWEA PO Box 163093 Columbus, OH 43216-3093. Phone: 614-645-1239, email: [mlclark@columbus.gov](mailto:mlclark@columbus.gov)

**Pre-registration until 4PM Sept 14<sup>th</sup>, 2017** online at [www.ohiowea.org](http://www.ohiowea.org) or by e-mail to Melodi Clark at [mlclark@columbus.gov](mailto:mlclark@columbus.gov).

Walk-up registrations are available for this event, but on-line registration is preferred. If unable to attend please honor your reservation with a check.

**COST:**

MEMBERS. free  
NON-MEMBERS free

**Details of and Directions to Jackson Pike WWTP Facilities:**

**Jackson Pike Treatment Plant:**

Located at 2104 Jackson Pike Columbus OH 43223 -

From SE(Marietta) Ohio to Jackson Pike WWTP:

Get on I-77 N in Muskingum Township from 3rd St, OH-60 N/Muskingum Dr and OH-821 N/Cambridge Rd Follow I-77 N and I-70 W to OH-104 S/Jackson Pike in Columbus  
Turn left onto OH-104 S/Jackson Pike

From Zanesville to Jackson Pike WWTP:

Take I-70 W. Drive to OH-104 S/Jackson Pike in Columbus  
Turn left onto OH-104 S/Jackson Pike

**Directions to 1250 Fairwood Ave from Jackson Pike WWTP.**

Head northeast on Jackson Pike toward Frank Rd/Frank-Refugee Expy  
Turn right onto OH-104 N  
Take the Lockbourne Rd exit  
Turn left onto Lockbourne Rd  
Turn right onto Frebis Ave  
Turn left onto Fairwood Ave

**LUNCH SPONSORED BY  
THOMAS SCIENTIFIC**