

**SEOWEA LAC Meeting**  
**Monday May 4th, 2015 – Yellow Springs, Ohio**

---

**Hosts:** YSI Yellow Springs  
YSI Yellow Springs  
**ELECTRONIC PRE-REGISTRATION  
PREFERRED**

---

**Check-In:** YSI  
8:00-8:15

---

**Technical Session** Online Process monitoring for  
Ammonium and Nitrate  
8:30-9:30 Robert Smith YSI (1.0 ct hrs)

9:30-10:30 How to troubleshoot nitrification and  
denitrification with the online  
Ammonium and nitrate sensors.  
Jon Van Dommelen Ohio EPA(1.0 ct hrs )

10:30-12:00 Travel to Yellow Springs Wastewater  
Facility. Tour of Wastewater Facility and  
discussion of online Ammonium and  
Nitrate sensors.  
  
Robert Smith YSI (1.0ct hrs)

---

**Lunch:** YSI Sponsored  
12:00-1:00 1700 Brannum Ln  
Yellow Springs, OH 45387  
937-767-7241 ext 246  
  
Menu:

---

**Business Meeting:** Committee business  
12:00

**Technical Session**  
1:00-1:45 *ISE Sensors*  
Laura St. Pierre, YSI (0.75 ct hr)

**Tour** YSI Facility Tour  
1:45-2:30 YSI (0.75 ct hrs)

Total Contact Hours 4.00

---

Tour, lunch and technical session is free for first time attendees.

P.O. forms can be addressed to the attention of Brenda Vanleave at Southeast Section OWEA PO Box 163093 Columbus, OH 43216-3093. Phone: 614-898-7100, email: [bvanleave@msconsultants.com](mailto:bvanleave@msconsultants.com)

**Pre-registration until 4PM April 30, 2015** online at [www.ohiowea.org](http://www.ohiowea.org) or by e-mail to Melodi Clark at [mlclark@columbus.gov](mailto:mlclark@columbus.gov).

Walk-up registrations are available for this event, but on-line registration is preferred. If unable to attend please honor your reservation with a check.

**COST:**  
MEMBERS. Free-/person  
NON-MEMBERS Free- (includes Section membership)

**Details of and Directions to YSI Facilities:**

**YSI Facilities:**  
Located at 1700/1725 Brannum Lane, Yellow Springs, OH 45387 -

From East to YSI:  
Take I-70W merge onto US-68S via Exit 52A toward Xenia. Turn right onto Brannum Ln. 1700/1725 Brannum Ln is on the right

From Southeast to YSI:  
Take I-77N to I-70W merge onto I-70W via Exit 44B on the left toward Columbus. Merge onto US-68 S via Exit 52A toward Xenia. Turn right onto Brannum Ln. 1700/1725 Brannum Ln is on the right.