City of Columbus Large Diameter Sewer Condition Assessment: Program Development and Updates to Approach February 28, 2013





DEPARTMENT OF PUBLIC UTILITIES Nick Domenick, P.E. – City of Columbus DPU Jeremy Cawley, P.E. – City of Columbus DPU Matt Kiefer, P.E. – Chester Engineers

What We'll Cover Today

- Program Development and History
- Alternatives Development with Risk-Based Consideration/Recommendations
- Lessons Learned
 - Future Direction of Program



Program Development and History



History of the Large Diameter Condition Assessment

- Consent Order Related
 - 8.j, "identifying and prioritizing structural deficiencies and identifying and implementing short-term and long-term rehabilitation actions to address each deficiency".
- Initiated Study in 2005
- Initial Approach
 - Cleaning costs averaged to \$39 per LF
 - Cleaning = \$26 per LF
 - CCTV = \$13 per LF
- Assess-First Approach
 - Sewers may not "need" 100% cleaning



Assess First Theory

- Sewers may not "need" 100% cleaning
- Utilize a risk-based approach to prioritize critical trunk mains
- Release a single large-diameter project annually
 - CCTV the entire trunk length without conducting cleaning
 - Assess the need for repairs and/or cleaning
 - Perform detailed design of repairs and/or cleaning



Assess-First Theory Costs

- Costs savings potential
 - Alum Creek North (Total Length 35,500 LF)
 - Cost to clean w/CCTV entire length = \$1,384,500
 - Cost to CCTV entire length w/50% cleaning assumed = \$1,015,300


Costs to complete Assess-First Theory

- Alum Creek North
 - \$600,000 to conduct high definition CCTV, sonar, manhole inspection, survey and assessment.
 - \$250,000 to complete design of all repairs and cleaning.
 - \$6,000,000 estimated to complete necessary repairs.
 - » No stand-alone cleaning required



Large Diameter Pipe Condition Assessment & Cleaning Prioritization Program

- Program Initiated in 2006
- Included all sanitary main trunk sewers (larger than 36" dia.)






2006 Prioritization Report

Foundation For Large Diameter Sewer Maintenance


- All trunk lines within the system (>36 inches)
- "Desktop" Indicator parameters





Likelihood of Failure

- Age (1-5)
- Material (1-5)
- Velocity / grade changes (1-5)
- Wastewater Strength/Pump Stations (1-5)
- Historical Info (1-5)
- Hydraulic Rating (1-5)





Consequence of Failure - Triple Bottom Line

- Size or Diameter (1-5)
- Depth (1-5)
- Specific Location (1-5)
 - Water Body/Wetland
 - Highway/Railroad/Building/ Cemetery
- General Location (1-5)
 - Land Use/Accessibility/
 Social Disruption





Prioritization of Trunk Sewers

Sewer Run	Recommended Priority		
Alum Creek Trunk Sewer - North	1		
Alum Creek Subtrunk	1a		
Alum Creek Trunk Sewer - Middle	2		
Alum Creek Interceptor Sewer	2a		
Alum Creek Trunk Sewer - South	3		
Big Walnut Trunk Sewer - North	4		
Big Walnut Trunk Sewer - Middle	5		
Big Walnut Trunk Sewer - South	6		
Olentangy Main Trunk Sewer	7		
Deshler Tunnel	8		
OSIS - Jackson Pike	9		
Milo Grogan Separation	10		
Upper Scioto Area NW Branch	11		
Interconnecting Trunk Sewer - North	12		
Interconnecting Trunk Sewer - South	13		
Blacklick Creek Main Trunk Sewer - North	14		
Blacklick Augmentation Sewer	15		
Blacklick Creek Main Trunk Sewer - South	16		
Blacklick Creek Sanitary Subtrunk	16a		
Big Run Trunk Sewer	17		
Scioto Main Trunk Sewer - North	18		
Upper Scioto West Interceptor Sewer	19		
Scioto Main Trunk Sewer - Middle	20		

20 years to complete the LDCA program

٠

٠

- Have completed 4 assessments to date
- Deriving inspection and maintenance schedules for the completed trunk sewers.



THE CITY OF

Alternatives Development with Risk-Based Consideration/Recommendations



Questions to Answer

- What is the current state of the sewer?
 - What condition is it in?
 - What is the remaining useful life (RUL)?
- What is the required level of service (LOS)?
- What are the critical sewer segments?
 - What is the likelihood of failure (LoF)?
 - What is the cost of repair / consequence of failure (CoF)?
- What are the best Capital and/or O&M Strategies?



Overall Process

- 1. Condition Assessment
- 2. Level of Service
- 3. Remaining Useful Life
- 4. Criticality
- 5. Life Cycle Costing / Valuation
- 6. Evaluate various Capital and/or Maintenance Strategies



Condition Assessment – Project Background

- 42" to 78" Reinforced Concrete Pipe
- 45 years old
- Nearly 40,000 LF
- Average 600' between manholes
 - Maximum at 1,700'
- Passes under I-270, S.R. 161
- Follows closely to Alum Creek
- Has never been inspected





Condition Assessment – Inspection Plan

Develop inspection plan

- Review existing information
- Field locate manholes
- Inspection method / technology
 - Track steered crawler, CCTV, Sonar

Contents

- Mapping
- Sewer information
 - (depth, length, size, material, etc)
- Access manholes
- Traffic control
- Right-of-entry





THE CITY OF

Condition Assessment – Sewer Inspection

- Planning was worthwhile
- NASSCO defect coding was performed





Condition Assessment – Sewer Inspection



Structural

- Overall fair
 - Average NASSCO score: 3.8
- Some segments in poor condition
- Common defects
 - Surface Reinforcement Visible (SRV)
 - Surface Aggregate Visible (SAV)
 - Surface Spalling (SSS)
 - Surface Roughness Increased (SRI)
- Erosion corrosion / erosion at spring line




Condition Assessment – Sewer Inspection

Sediment Depth (inches)AverageMaximumMinimum1.13.60.0

0&M

- Overall good
- Less sediment than expected
- Less I/I than expected
- One partially blocked section





Condition Assessment – Sewer Inspection	¥	Ftg. Code Description 0.0 AMH Access Point - Manhole 0.0 MWL Water Level 0.0 SRV Surface: Reinforcement Visible 21.0 MGO General Observation
 QA/QC of defect coding was essential 		
 Scoring prior to QC was much lower due to missed codes in the field 		•103.9 MGO General Observation
 Coding must consistent between the trunk sewers 		•162.5 MGO General Observation
• QA/QC in field can save time and avoid re-work	*	
		•361.8 IR Infiltration - Runner •361.8 MGO General Observation
	(440.9 SRV Surface: Reinforcement Visible 441.0 AMH Access Point - Manhole



Level of Service

Need to define the goal we are trying to accomplish

- Maximize hydraulic capacity originally designed for
- Prevent interruption to service

Identify Failure Modes


- Structural integrity must not affect capacity
 - Collapse, leakage, etc.
- O&M issues must not affect capacity
 - Sediment build up
 - Minor sediment observed
 - Inflow & Infiltration (I/I)
 - Minor I/I observed



Remaining Useful Life


Critical in cost analysis for estimate LoF

- NASSCO PACP Method
- National Resource Council Canada
- Site Specific Decay Curves



Source: MIIP Report: The State of Canadian Sewers – Analysis of Asset Inventory and Condition

NASSCO PACP Pipe Grades				
Grade 1	Failure is unlikely in the foreseeable future.			
Grade 2	Risk of failure within 20 years.			
Grade 3	Risk of failure within 10-20 years.			
Grade 4	Risk of failure within 5-10 years.			
Grade 5	Risk of failure within 5 years.			



COLUMBUS

DEPARTMENT OF PUBLIC UTILITIES

THE CITY OF

Remaining Useful Life

Three methods were compared

Remaining Useful Life				
Condition Grade/SPG	NASSCO* Model	Regression Model	Site Specific Model	
1.0	40	120	78	
1.5	40	80	78	
2.0	20	63	78	
2.5	20	50	70	
3.0	20	40	42	
3.5	14	29	25	
4.0	10	21	14	
4.5	7	13	6	
5.0	5	6	0	



Remaining Useful Life

Challenges with using NASSCO when estimating RUL

- Use the PACP index or maximum score?
- PACP index does not "code" good condition
- It is possible to code overlapping defects
 - Surface Spalling (SSS) Grade 2
 - Surface Aggregate Visible (SAV) Grade 3



Criticality

- Likelihood of Failure (LoF)
 - 1 / RUL
 - 1/5 = 20% annual chance of occurence
- Consequence of Failure (CoF)
- Business Risk Exposure
- LoF x CoF = Business Risk Exposure



Criticality – Consequence of Failure

Economic

- Diameter
- Average depth
- Under a body of water
- Under road
- Under structure or building
- Under railroad track
- Land use
- Accessibility
- Emergency work premium

Social

- Property damage potential from WIB or SSOs
- Social disruption potential

Environmental

- Cleanup
- EPA Fines



Criticality – Consequence of Failure

A few examples...

Traffic Disruption

- 120,000 veh/ day x (10 min / veh) x (1 hr / 60 min) x \$45 / hr x 2 days = \$1.8 Million
 - Interstate \$1.8 Million
 - Major Road \$1.1 Million
 - Minor Road \$300,000

Sewer Backup

- 50 households affected, \$2,000 per household
- \$100,000 per event



Life Cycle Costing

Alternatives

- Do Nothing
- Spot Repair
- Lining
- Replacement
- Combination

Direct Costs Risk Costs

- Operation
 - Economic
- Maintenance
 Social
- Renewal
- Environmental



Life Cycle Costing

Net Present Value


- Annual Costs
 - Capital, O&M, Risk

Benefit Cost Ratio

• Benefit is reduced risk



Life Cycle Costing





Sensitivity Analysis

Variables with a significant impact on the financial analysis :

- Estimate of remaining useful life
- Average vs. maximum sewer segment condition grade (SPG)
- Risk costs
- Interest rate
- Useful Remaining Life estimation based on the Decay Curve model, NRC Deterioration Regression model and NASSCO model for remaining useful life model results
- Sewer segment condition rating based on the average and maximum structural condition (SPG)
- Significantly increase and decrease the risk costs
- Significantly increase and decrease the interest rate




Capital / O&M Strategies

- Perform cementitious spot repairs whenever possible
- Selectively line sewers in poor condition when spot repairs are numerous



Capital / O&M Strategies





Future Direction of Program



Process Refinement

- 4 Assessments Completed
 - Scioto Main/West Side Relief
 - Olentangy Main
 - Alum Creek Trunk (North)/Alum Creek Subtrunk
 - Alum Creek Trunk (Middle)/Alum Creek Interceptor
- Results Comparison
 - Utilize lessons learned from previous projects
 - Review need for technologies used; i.e. high def CCTV, sonar, laser, etc.
 - Review and utilize emerging technologies



Debris Accumulation (Sonar)

- Not as much as expected
- Unit prices for cleaning not any better
- Inspections are snapshot in time Material wasn't there





Laser Data

- Difficult to estimate RUL
- Comparing to future inspections is unlikely (only paper reports provided)
- Most advantageous for undocumented curves, deflected brick sewers, and sliplining projects





Good Old Fashioned Man-Entry!

- Debris Volumes estimated at manholes; 10 foot intervals
- Helps determine full extent of repair areas
- Cost comparable
- Localizes labor






Delaying Detailed Design Process

- Pipes simply weren't that bad
- Exposed rebar does not mean imminent collapse
- Defects were predominantly category 3's
- NASSCO scoring reduced 5's to 4's for several corrosion codes
- Back to the roots of the program
- Pipes have corrosion/scaling, but are structurally sound
- Work is focused and well-defined, yet still not competitively bid
- Eases perceptions of designer liability and resulting conservatism



Delaying Detailed Design Process

- Instead of "Find & Fix";
 "Find, <u>Prioritize</u>, & <u>then</u> Fix"
- Rehab can be prioritized within context of the entire system
- Better packages of work grouped together
- SCREAM Model
 - Consistency/Uniformity
- Tailored
- Speed
 - Condition Rating and Overall Project





Accelerated Inspection Timelines

- Reduced costs and reallocated detailed design funds
- Reduced 20 year program down to 10
- Added in downtown combined sewers including OSIS
- Not tackling storm yet

Old Process

Length: 40,000 LF Assessment: \$600K Design:\$400K Construction: \$5M

VS.

New Process

Length: 120,000 LF Assessment: \$1.2M Design: Delayed Construction: Delayed



Pole Camera Inspections


- Cursory Evaluation of system
- Cheaper and faster than traditional inspections
- No individual defect coding, but can be incorporated into GIS
- "Sample" inspections can be extrapolated






Pole Camera Inspections

• Allows for further prioritization of inspections (Lowers overall risk)




Extrapolation of Results

- SCREAM modeling
- Sample size may not be large enough yet







Rehab Methods

- Traditional
 - Spot Repairs (\$200/SF)
 - CIPP
 - Shotcrete
 - Sliplining & Segmented panels





Rehab Methods

- Non-Traditional
 - 2-in cement layer nozzle gun
 - 2-in cement layer centrifugally spun
 - Spiral wound pipe





Design/Build

- Receive proposals and select the best approach not just the lowest cost
- Leverages the experience and creativity of the contractors
- Scioto Main 120" Rehab





Summary

- Sonar & laser have their place and should be used where appropriate
- Stepwise approach more cost effective for procuring services
- Make rehab materials compete against one another
- Essence of Asset Management is "continuous improvement"
- Use the data obtained to make better decisions about future work



Thanks!





THE CITY OF COLUMBUS MICHAEL B. COLEMAN, MAYOR

DEPARTMENT OF PUBLIC UTILITIES

Questions?